

IMGING

INSPECTION REPORT

4405 WEST GULF DRIVE
SANIBEL, FL 33957

02/14/2023



Inspection Report Summary



Property Information

Job Name

Job Type
Residential

Phone Number
 N/A

Email Address
 N/A

About This Report

Report Created
02/14/2023

Assets
21

 Added Photos
0

 Annotations
1

 Images With Confirmed Damage
20

General Information

Completed by
Connery Schiebel

Completed on
02/14/2023

Inspect List Type
 N/A





AT002-1 OTHER

Annotated by Connery Schiebel on
 02/14/2023 2:33 PM EST

Additional Notes


Connery Schiebel
 02/14/2023 2:36 PM EST

Moisture Intrusion: Moisture intrusion is a common issue in flat roofs, and it can lead to significant damage if left untreated. With out thermal drone, you can detect areas of the roof where moisture has infiltrated. These areas will appear at a higher temperature than the surrounding areas, indicating a potential water leak.



AT008


CLOSE UP EXAMPLES




CONFIRMED DAMAGE
 Ponding Water

8


NOTE






AT032

CLOSE UP EXAMPLES




NOTE



CONFIRMED DAMAGE


Ponding Water

10




AT042

CLOSE UP EXAMPLES




NOTE



CONFIRMED DAMAGE


Ponding Water

4




AT034

CLOSE UP EXAMPLES




NOTE




CONFIRMED DAMAGE
 Ponding Water

14




AT016

CLOSE UP EXAMPLES




NOTE




CONFIRMED DAMAGE
 Ponding Water

7




AT018

CLOSE UP EXAMPLES




NOTE



CONFIRMED DAMAGE


Ponding Water

7




AT010

CLOSE UP EXAMPLES




NOTE



CONFIRMED DAMAGE


Ponding Water

2



AT020

CLOSE UP EXAMPLES




NOTE

CONFIRMED DAMAGE


Ponding Water

3



AT028

CLOSE UP EXAMPLES





NOTE

CONFIRMED DAMAGE

Ponding Water

5






CONFIRMED DAMAGE
 Ponding Water



6

AT044

CLOSE UP EXAMPLES



NOTE




CONFIRMED DAMAGE
 Ponding Water


2


AT012

CLOSE UP EXAMPLES




NOTE






AT024

CLOSE UP EXAMPLES




NOTE




CONFIRMED DAMAGE
 Ponding Water

5




AT036

CLOSE UP EXAMPLES




NOTE




CONFIRMED DAMAGE
 Ponding Water

7




AT048

CLOSE UP EXAMPLES




NOTE



CONFIRMED DAMAGE


Ponding Water

10




AT002

CLOSE UP EXAMPLES




NOTE



CONFIRMED DAMAGE


Ponding Water

8




AT030

CLOSE UP EXAMPLES




NOTE




CONFIRMED DAMAGE
 Ponding Water

11




AT014

CLOSE UP EXAMPLES




NOTE




CONFIRMED DAMAGE
 Ponding Water

4



AT040

CLOSE UP EXAMPLES




NOTE

CONFIRMED DAMAGE

Ponding Water

11



Google